# **MATERIAL SAFETY DATA SHEET**

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

DATE OF PREP OCTOBER 1983

#### Section I

MANUFACTURER'S NAME BOSTIK WEST/DIVISION OF USM CORPORATION/EMHART

STREET ADDRESS 20846 SOUTH NORMANDIE AVENUE CITY. STATE. AND ZIP CODE TORRANCE, CALIFORNIA 90502

EMERGENCY TELEPHONE NO.

(213)320-6800

PRODUCT CLASS

**EPOXY** 

DN9335, INSIGNIA WHITE

TRADENAME BOSTIK

MANUFACTURERS CODE IDENTIFICATION 443-3-R66

Catalyst: X-304

Mix Ratio: 3 parts 443-3-R66 (BASE)

to 1 part X-304 by volume.

### Section II — HAZARDOUS INGREDIENTS

INGREDIENT 443-3-R66 (BASE ONLY)	CAS NO.	PERCENT (WT.)	TI PPM	mg/M³	LEL	VAPOR PRESSURE
METHYL ETHYL KETONE	78-93-3	20-25	200		1.8	90
TOLUENE	108-88-3	5-10	200		1.2	22
XYLENE	1330-20-7	<b>&lt;</b> 5	100		1.0	7
N. BUTYL ACETATE	123-86-4	<b>&lt;</b> 5	150		·1.7	8 .
BUTYL CELLOSOLVE	111-76-2	<b>&lt;</b> 5	50		1.1	1
N. BUTYL ALCOHOL	71-36-3	<b>&lt;</b> 1	100		1.7	4
CHROMATE COMPOUNDS AS:						
. Pb	7439-92-1	<0.20		0.05		
Cr	7440-47-3	<0.05		0.05		
NOTE: Epichlorohydrin (ECH) content is less than 1-2 ppm.						

#### Section III — PHYSICAL DATA

BOILING RANGE	176° - 34	0° F.	VAPOR DENS	ΙΤΥ	XX HEAVIER	LIGHTER, THAN AIR	
EVAPORATION RAT	E FASTI	ER XX SLOWER, THAN ETHER	PERCENT VOLATILE BY VOLUME	57%	WEIGHT PER GALLON	9.9 1bs.	

#### Section IV — FIRE AND EXPLOSION HAZARD DATA

DOT CATEGORY RED LABEL, FLAMMABLE (MIN.)
FLASH POINT 23° F. TAG CLOSED CUP

LEL 1.0

EXTINGUISHING MEDIA

EXCLUDE AIR - USE FOAM, CO2, STEAM, WATER FOG, DRY CHEMICALS. DO NOT USE WATER.

UNUSUAL FIRE AND EXPLOSION HAZARDS

VAPOR FORMS EXPLOSIVE MIXTURE WITH AIR BETWEEN UPPER AND LOWER EXPLOSION LIMITS.

SPECIAL FIRE FIGHTING PROCEDURES

DO NOT USE WATER, EXCLUDE AIR, USE WATER SPRAY TO COOL FIRE EXPOSED SURFACES AND TO PROTECT PERSONNEL.

Se	ction	HEA		DE	ATA	1
: - :-	TY	 	 	 		

See Section II THRESHOLD LIMIT VALUE :

EFFECTS OF OVEREXPOSURE Headache, nausea, dizziness. Breathing vapor will be irritating to nose,

throat and eyes.

Emergency and first aid procedures: Skin Exposure: Wash affected area with soap & water.

Eye Exposure; Flush with water for at least 15 minutes, consult physician.

Ingestion: Consult physician immediately.

Inhalation: Remove victim to fresh air, consult physician.

Section VI — REACTIVITY DATA				
STABILITY	UNSTABLE	XXX STABLE	conditions to Avoid: Storage at high temperatures.	
Incompata	ability(Mater	ials to avoid):	_ Strong oxidizing agents. Sparks and open flame.	
Hazardous	s Decompositi	on Products: (	n combustion co co. Aldohydos and other expenses land summer	

Hazardous Decomposition Products:

on CO, CO<sub>2</sub>, Aldenydes and other organics, lead fumes oxides of nitrogen.

HAZARDOUS POLYMERIZATION CONDITIONS TO AVOID

MAY OCCUR

XXX WILL NOT OCCUR

## Section VII — SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Eliminate sources of ignition and clear fumes from area Prevent liquid from entering sewers, water sources, or low areas. Keep unnecessary personnel away. Shut off source, if possible to do so without hazard. Contain spilled liquid with sawdust, sand or oil absorbing compound. Wash area with detergent & water.

Consult disposal expert & ensure conformity with local regulations.

## Section VIII — SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION . Use approved respiratory protection such as an air-supplied mask if used in

non-ventilated area.

Mechanical: Explosion-proof ventilation equipment. No smoking or open lights.

Face velocity 60 fpm in confined area.

Protective gloves: Chemically resistant gloves.
EYE PROTECTION: Chemical splash goggles or face shield. OTHER PROTECTIVE EQUIPMENT : Eye bath & safety shower.

## Section IX — SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING. Keep containers closed when not in use. Do Not handle or store near flame, heat or strong oxidants. Adequate ventilation required. Containers of this product may be hazardous when emptied - these containers retain product residues ( vapor, liquid, OTHER PRECAUTIONS

All handling equipment should be electrically grounded. Treat as a very flammable liquid.

Lee A. Dickinson Technical Service Manager